

Ericsson Access Switch ALARM_8894 Critical Alarm Resolution SOP

Node: Ericsson-Access-Bangalore-KA-84 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_8894

Description

This SOP outlines the steps to diagnose and resolve the Critical Alarm ALARM_8894 on Ericsson Access Switch Node ID: Ericsson-Access-Bangalore-KA-84

Potential Root Causes

Cause	Probability
High CPU utilization due to software bug	High
Misconfigured network interface	Medium
Hardware failure	Low

Diagnostic Commands

```
show tech-support
show cpu-usage
show interface | include errors
show alarm-history
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU utilization', 'Action': 'Run show cpu-usage command to check CPU utilization', 'CLI_Command': 'show cpu-usage'}
- Step 2: {'Step': '2. Check software version', 'Action': 'Verify software version for any known bugs', 'CLI_Command': 'show version'}
- Step 3: {'Step': '3. Reconfigure network interface', 'Action': 'Reconfigure network interface to correct settings', 'CLI_Command': 'interface , no shutdown'}
- Step 4: {'Step': '4. Check hardware logs', 'Action': 'Check hardware logs for any error messages', 'CLI_Command': 'show hardware-logs'}
- Step 5: {'Step': '5. Reboot the node', 'Action': 'Perform a soft or hard reboot of the node', 'CLI_Command': 'system reboot'}

Post-Check Verification

```
show cpu-usage  
show interface | include errors  
show alarm-history
```