

Ericsson Access Switch ALARM_2042 Critical Alarm SOP

Node: Ericsson-Access-Chennai-TN-102 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_2042

Description

ALARM_2042 Critical Alarm on Ericsson Access Switch (Node ID: Ericsson-Access-Chennai-TN-102) due to a severe hardware issue.

Potential Root Causes

Cause	Probability
Hardware failure in the Access Switch	High
Software malfunction due to firmware mismatch	Medium
Power supply issues affecting the Access Switch	Low

Diagnostic Commands

```
show system alarm
show hardware status
show power supply status
show firmware version
```

Resolution Steps

- Step 1: {'Step': 'Power cycle the Access Switch', 'Action': "Issue the command: 'power off' followed by 'power on' to restart the device."}
- Step 2: {'Step': 'Replace the faulty hardware component', 'Action': "Identify and replace the faulty hardware component as per Ericsson's maintenance guidelines."}
- Step 3: {'Step': 'Update the firmware to the latest version', 'Action': "Issue the command: 'firmware update' to update the firmware to the latest version."}
- Step 4: {'Step': 'Verify power supply health', 'Action': "Issue the command: 'show power supply status' to verify the power supply health."}

Post-Check Verification

```
show system alarm
show hardware status
```

```
show power supply status  
show firmware version
```