

Ericsson Access Switch ALARM_3322 Warning Severity SOP

Node: Ericsson-Access-Chennai-TN-102 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_3322

Description

This SOP outlines the procedures to diagnose and resolve ALARM_3322 on Ericsson Access Switch Node ID: Ericsson-Access-Chennai-TN-102

Potential Root Causes

Cause	Probability
High Temperature in the Node	High
Faulty Cooling System	Medium
Overloaded System Resources	Low

Diagnostic Commands

```
show system resource
show temperature
show system faults
```

Resolution Steps

- Step 1: {'Step': 'Check System Resources', 'Action': "Run 'show system resource' command to identify overloaded resources", 'CLI_Command': 'show system resource'}
- Step 2: {'Step': 'Verify Temperature', 'Action': "Run 'show temperature' command to verify temperature levels", 'CLI_Command': 'show temperature'}
- Step 3: {'Step': 'Reset System Resources', 'Action': "Run 'reset system resource' command to reset overloaded resources", 'CLI_Command': 'reset system resource'}
- Step 4: {'Step': 'Check Cooling System', 'Action': 'Verify if cooling system is faulty and replace if necessary', 'CLI_Command': ''}

Post-Check Verification

```
show system resource
show temperature
show system faults
```