

Ericsson Access Switch Chennai TN-102 SOP for Alarm ALARM_6169

Node: Ericsson-Access-Chennai-TN-102 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_6169

Description

This SOP outlines the steps to diagnose and resolve a Critical alarm ALARM_6169 on the Ericsson Access Switch Chennai TN-102.

Potential Root Causes

Cause	Probability
Hardware failure	High
Software bug	Medium
Configuration issue	Medium
Faulty interface	Low

Diagnostic Commands

```
show tech-support
show system redundancy
show interface detail
show log
```

Resolution Steps

- Step 1: {'Step': 'Check system redundancy', 'Action': "Run the command 'show system redundancy' to verify the status of the system redundancy.", 'CLI_Command': 'show system redundancy'}
- Step 2: {'Step': 'Replace faulty hardware', 'Action': 'Replace the faulty hardware component and verify the alarm is cleared.', 'CLI_Command': 'no shutdown'}
- Step 3: {'Step': 'Update software', 'Action': 'Update the software to the latest version and verify the alarm is cleared.', 'CLI_Command': 'install software '}
- Step 4: {'Step': 'Check configuration', 'Action': 'Verify the configuration and correct any discrepancies.', 'CLI_Command': 'show configuration'}
- Step 5: {'Step': 'Swap faulty interface', 'Action': 'Swap the faulty interface with a spare interface and verify the alarm is cleared.', 'CLI_Command': 'interface no shutdown'}

Post-Check Verification

```
show system redundancy
show interface detail
show log
show tech-support
```