

Ericsson Access Switch Emergency Response Procedure (ALARM_7693)

Node: Ericsson-Access-Chennai-TN-102 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_7693

Description

This SOP outlines the steps to be taken in response to a Critical Alarm (ALARM_7693) on the Ericsson Access Switch (Node ID: Ericsson-Access-Chennai-TN-102).

Potential Root Causes

Cause	Probability
High CPU utilization due to software bugs	High
Hardware failure in the Access Switch	Medium
Misconfigured switch settings	Low

Diagnostic Commands

```
show sys alarm
show cpu utilization
show interface statistics
show config
```

Resolution Steps

Step 1: {'Step': '1. Check the system logs for any error messages related to the alarm', 'Action': 'show sys log'}

Step 2: {'Step': '2. Verify the CPU utilization and check for any software bugs', 'Action': 'show cpu utilization'}

Step 3: {'Step': '3. Check the interface statistics for any errors or inconsistencies', 'Action': 'show interface statistics'}

Step 4: {'Step': '4. Verify the switch configuration and check for any misconfigurations', 'Action': 'show config'}

Step 5: {'Step': '5. If the issue persists, perform a hardware reset of the Access Switch', 'Action': 'reset system'}

Post-Check Verification

```
show sys alarm (verify the alarm has cleared)
show cpu utilization (verify CPU utilization is within normal limits)
show interface statistics (verify interface statistics are within
normal limits)
show config (verify switch configuration is correct)
```