

Ericsson Access Switch Chennai TN-102

ALARM_9497 Minor Alarm Resolution SOP

Node: Ericsson-Access-Chennai-TN-102 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_9497

Description

This SOP outlines the steps to diagnose and resolve the ALARM_9497 minor alarm on Ericsson Access Switch Node ID Ericsson-Access-Chennai-TN-102.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Insufficient Memory	Medium
Router Software Issue	Low

Diagnostic Commands

```
show cpu utilization
show memory statistics
show version
show log
```

Resolution Steps

- Step 1: {'Step': 'Verify CPU Utilization', 'Description': 'Check if CPU utilization is above the threshold value.', 'Action': 'show cpu utilization', 'Expected_Output': 'CPU utilization below threshold value.'}
- Step 2: {'Step': 'Check for Memory Issues', 'Description': 'Verify if memory is sufficient to run the system.', 'Action': 'show memory statistics', 'Expected_Output': 'Memory is sufficient.'}
- Step 3: {'Step': 'Upgrade Router Software', 'Description': 'Check if the router software is up-to-date.', 'Action': 'show version | include Software', 'Expected_Output': 'Software is up-to-date.'}
- Step 4: {'Step': 'Clear Log Buffer', 'Description': 'Clear the log buffer to prevent log buffer overflow.', 'Action': 'clear log buffer', 'Expected_Output': 'Log buffer cleared.'}

Post-Check Verification

```
show cpu utilization
show memory statistics
```

```
show version
```

```
show log
```