

Ericsson Access Switch ALARM_1681 SOP

Node: Ericsson-Access-Chennai-TN-104 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_1681

Description

Warning: High CPU utilization on Ericsson Access Switch in Chennai, TN (Node ID: Ericsson-Access-Chennai-TN-104)

Potential Root Causes

Cause	Probability
Insufficient CPU resources due to high traffic	High
Malfunctioning hardware component	Medium
Software issue or configuration problem	Low

Diagnostic Commands

```
show cpu utilization
show process list
show interface statistics
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU utilization and identify the top processes consuming resources', 'Action': "Use 'show cpu utilization' command to monitor CPU usage"}
- Step 2: {'Step': '2. Investigate and terminate any unnecessary processes', 'Action': "Use 'kill' command to terminate processes consuming excessive resources"}
- Step 3: {'Step': '3. Verify interface statistics to identify any issues with network traffic', 'Action': "Use 'show interface statistics' command to analyze interface statistics"}
- Step 4: {'Step': '4. Perform a hardware check to identify any malfunctioning components', 'Action': 'Run a hardware diagnostic test to identify any faulty components'}
- Step 5: {'Step': '5. Review and update software configuration to address any software issues', 'Action': "Use 'show configuration' command to review and update software configuration"}

Post-Check Verification

```
show cpu utilization
show process list
show interface statistics
```