

Ericsson Access Switch - ALARM_2877 Warning SOP

Node: Ericsson-Access-Chennai-TN-104 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_2877

Description

Alarm triggered on Ericsson Access Switch Node Ericsson-Access-Chennai-TN-104 due to a warning condition.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Glitch	Medium
Environmental Factors	Low

Diagnostic Commands

```
admin show alarm info
admin show system status
admin show interface status
```

Resolution Steps

- Step 1: {'Step': 'Restart the Access Switch', 'Action': 'admin restart'}
- Step 2: {'Step': 'Check and replace faulty hardware components', 'Action': 'admin show hardware status'}
- Step 3: {'Step': 'Update software to latest version', 'Action': 'admin software update'}

Post-Check Verification

```
admin show alarm info
admin show system status
admin show interface status
```