

Ericsson Access Switch SOP: Alarm Code

ALARM_3487

Node: Ericsson-Access-Chennai-TN-104 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_3487

Description

This SOP outlines the procedures for resolving a critical alarm on Ericsson Access Switch Node ID: Ericsson-Access-Chennai-TN-104.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Bug	Medium
Configuration Issue	Low

Diagnostic Commands

```
show alarm status
show tech-support
show version
show running-config
```

Resolution Steps

- Step 1: {'Step': '1. Check the alarm status', 'Action': 'Run the command: show alarm status'}
- Step 2: {'Step': '2. Gather technical support information', 'Action': 'Run the command: show tech-support'}
- Step 3: {'Step': '3. Verify the software version', 'Action': 'Run the command: show version'}
- Step 4: {'Step': '4. Check the configuration', 'Action': 'Run the command: show running-config'}
- Step 5: {'Step': '5. Perform a hardware check', 'Action': 'Check for any visible signs of hardware failure'}
- Step 6: {'Step': '6. Apply software patch if necessary', 'Action': 'Run the command: install software '}
- Step 7: {'Step': '7. Review and correct configuration if necessary', 'Action': 'Run the command: configure replace '}

Post-Check Verification

```
show alarm status
show version
show running-config
```