

Standard Operating Procedure for Ericsson Access Switch (Node ID: Ericsson-Access-Chennai-TN-104) - ALARM_7580

Node: Ericsson-Access-Chennai-TN-104 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_7580

Description

Critical Alarm on Ericsson Access Switch (Node ID: Ericsson-Access-Chennai-TN-104) - ALARM_7580. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Glitch	Medium
Configuration Issue	Low

Diagnostic Commands

```
show system status
show system logs
show interface status
show cpu usage
show memory usage
```

Resolution Steps

- Step 1: {'Step': '1. Power cycle the access switch', 'CLI_Command': 'reload'}
- Step 2: {'Step': '2. Check and replace faulty hardware (if applicable)', 'CLI_Command': 'show system status | include Faulty'}
- Step 3: {'Step': '3. Update software (if applicable)', 'CLI_Command': 'software update check'}
- Step 4: {'Step': '4. Verify and correct configuration (if applicable)', 'CLI_Command': 'show configuration'}

Post-Check Verification

```
show system status | include Normal
show system logs | include No errors
```

```
show interface status | include Up  
show cpu usage | include Normal  
show memory usage | include Normal
```