

Ericsson Access Switch Chennai TN-104

ALARM_8275 SOP

Node: Ericsson-Access-Chennai-TN-104 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_8275

Description

This SOP outlines the procedures for identifying, diagnosing, and resolving the ALARM_8275 critical alarm on the Ericsson Access Switch Chennai TN-104.

Potential Root Causes

Cause	Probability
High CPU utilization due to software bugs or configuration issues	High
Hardware failure or malfunctioning components	Medium
Misconfigured or faulty interfaces	Low

Diagnostic Commands

```
show system status
show cpu utilization
show interface status
show alarm history
```

Resolution Steps

- Step 1: {'Step': 'Restart the Access Switch', 'Action': 'sudo shutdown -r now'}
- Step 2: {'Step': 'Verify CPU utilization and interface status', 'Action': ['show cpu utilization', 'show interface status']}
- Step 3: {'Step': 'Clear alarm history and restart the Access Switch', 'Action': ['clear alarm history', 'sudo shutdown -r now']}
- Step 4: {'Step': 'Replace faulty or malfunctioning hardware components', 'Action': ['replace hardware components', 'sudo shutdown -r now']}
- Step 5: {'Step': 'Reconfigure or reset interfaces', 'Action': ['reconfigure interfaces', 'sudo shutdown -r now']}

Post-Check Verification

```
show system status
```

```
show cpu utilization
show interface status
show alarm history
```