

Ericsson Access Switch Alarm Procedure:

ALARM_9418

Node: Ericsson-Access-Chennai-TN-104 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_9418

Description

ALARM_9418 is a Warning alarm indicating a potential issue with the Ericsson Access Switch Node ID: Ericsson-Access-Chennai-TN-104.

Potential Root Causes

Cause	Probability
High power consumption due to malfunctioning optics	High
Incorrect configuration settings	Medium
Hardware failure in the switching module	Low

Diagnostic Commands

```
show clock
show version
show inventory
show interface GigabitEthernet 0/0/0
show optics
```

Resolution Steps

- Step 1: {'Step': 'Perform a restart of the Access Switch', 'Action': 'Restart the Access Switch using the command: "system restart now"}
- Step 2: {'Step': 'Verify power consumption', 'Action': 'Verify power consumption using the command: "show power consumption"}
- Step 3: {'Step': 'Check configuration settings', 'Action': 'Check configuration settings using the command: "show running-config"}
- Step 4: {'Step': 'Swap out hardware', 'Action': 'Swap out the malfunctioning hardware with a spare hardware unit'}

Post-Check Verification

```
show clock
```

```
show version
show inventory
show interface GigabitEthernet 0/0/0
show optics
```