

Ericsson Access Switch Alarm SOP: ALARM_9885

Node: Ericsson-Access-Chennai-TN-104 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_9885

Description

This SOP outlines the procedures to diagnose and resolve the Critical alarm ALARM_9885 on Ericsson Access Switch Node ID: Ericsson-Access-Chennai-TN-104.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Memory Leak	Medium
Software Bug	Low

Diagnostic Commands

```
show cpu utilization
show memory usage
show alarm history | include ALARM_9885
show tech-support
```

Resolution Steps

Step 1: {'Step': '1. Restart the node', 'Command': 'reload', 'Description': 'Attempt to restart the node to resolve the issue.'}

Step 2: {'Step': '2. Clear CPU and memory usage', 'Command': 'clear cpu stats', 'Description': 'Clear CPU and memory usage statistics to prevent further issues.'}

Step 3: {'Step': '3. Upgrade software', 'Command': 'upgrade software | confirm', 'Description': 'Upgrade the software to the latest version to resolve any software bugs.'}

Post-Check Verification

```
show cpu utilization
show memory usage
show alarm history | include ALARM_9885
show tech-support
```