

Access Switch Alarm Resolution SOP: ALARM_4698

Node: Ericsson-Access-Chennai-TN-92 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_4698

Description

Resolving ALARM_4698 on Ericsson Access Switch in Chennai, Tamil Nadu Node (Ericsson-Access-Chennai-TN-92)

Potential Root Causes

Cause	Probability
Physical layer issues	High
Software defects	Medium
Configuration errors	Low

Diagnostic Commands

```
show tech-support
show log info
show interface status
show controllers optic
```

Resolution Steps

- Step 1: {'Step': 'Verify physical connections and cable integrity', 'Action': 'Check all physical connections and cables for any signs of damage or wear and tear'}
- Step 2: {'Step': 'Run diagnostic tests', 'Action': '"Run the 'test optic' command to identify any issues with the optic module'"}
- Step 3: {'Step': 'Update software or firmware', 'Action': 'Check for any software or firmware updates and apply them if necessary'}
- Step 4: {'Step': 'Verify configuration', 'Action': 'Verify that the configuration is correct and that there are no errors'}
- Step 5: {'Step': 'Reset or replace the faulty component', 'Action': '"If the issue persists, reset or replace the faulty component as necessary'"}

Post-Check Verification

```
show tech-support
show log info
```

```
show interface status  
show system status
```