

Ericsson Access Switch Alarm Handling SOP: ALARM_6155

Node: Ericsson-Access-Chennai-TN-92 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_6155

Description

This SOP outlines the steps to diagnose and resolve ALARM_6155 on Ericsson Access Switch Node ID: Ericsson-Access-Chennai-TN-92.

Potential Root Causes

Cause	Probability
Hardware failure in the switch	High
Software issue due to configuration mismatch	Medium
Environmental factors such as power or temperature fluctuations	Low

Diagnostic Commands

```
show tech support
show alarm info
show environment
show power
```

Resolution Steps

- Step 1: {'Step': 'Perform a hardware check', 'Action': "Run 'show tech support' and 'show alarm info' to identify the affected components"}
- Step 2: {'Step': 'Verify software configuration', 'Action': "Run 'show configuration' and verify that the configuration is correct"}
- Step 3: {'Step': 'Replace faulty hardware (if identified)', 'Action': 'Replace the faulty hardware with a new one and verify the system is stable'}
- Step 4: {'Step': 'Reboot the switch', 'Action': "Run 'reboot' to restart the switch"}

Post-Check Verification

```
show alarm info
show tech support
show environment
```

show power