

Ericsson Access Switch Alarm SOP - ALARM_6316

Node: Ericsson-Access-Chennai-TN-92 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_6316

Description

This SOP outlines the procedures to diagnose and resolve the ALARM_6316 issue on the Ericsson Access Switch in Chennai, TN-92.

Potential Root Causes

Cause	Probability
High CPU utilization on the Access Switch	High
Misconfigured Quality of Service (QoS) settings	Medium
Outdated software versions	Low

Diagnostic Commands

```
show system alarm
show cpu utilization
show qos configuration
show version
```

Resolution Steps

- Step 1: {'Step': 'Check CPU utilization', 'Action': "Run 'show cpu utilization' command and analyze the output."}
- Step 2: {'Step': 'Verify QoS settings', 'Action': "Run 'show qos configuration' command and ensure that QoS settings are properly configured."}
- Step 3: {'Step': 'Update software versions', 'Action': "Run 'install software' command to update the software versions on the Access Switch."}
- Step 4: {'Step': 'Clear alarms', 'Action': "Run 'clear system alarm' command to clear the ALARM_6316 issue."}

Post-Check Verification

```
show system alarm
show cpu utilization
show qos configuration
show version
```