

Ericsson Access Switch - ALARM_6878 Warning SOP

Node: Ericsson-Access-Chennai-TN-92 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_6878

Description

This Standard Operating Procedure (SOP) is used to troubleshoot and resolve the ALARM_6878 warning alarm on the Ericsson Access Switch at the Chennai, Tamil Nadu, India location (Node ID: Ericsson-Access-Chennai-TN-92).

Potential Root Causes

Cause	Probability
Excessive packet loss on the uplink interface	High
Congestion on the uplink interface due to high traffic load	Medium
Misconfigured Quality of Service (QoS) settings	Low

Diagnostic Commands

```
show interface uplink status
show interface uplink counters
show qos profile
show traffic statistics
```

Resolution Steps

- Step 1: {'Step': '1. Check the uplink interface status and counters', 'Action': "Run the 'show interface uplink status' and 'show interface uplink counters' commands to verify the interface status and packet loss."}
- Step 2: {'Step': '2. Verify QoS profile settings', 'Action': "Run the 'show qos profile' command to verify the QoS settings and adjust them as necessary."}
- Step 3: {'Step': '3. Clear the uplink interface counters', 'Action': "Run the 'clear interface uplink counters' command to clear the counters and re-run the diagnostic commands."}
- Step 4: {'Step': '4. Verify traffic statistics', 'Action': "Run the 'show traffic statistics' command to verify the traffic load and adjust the QoS settings or uplink interface configuration as necessary."}
- Step 5: {'Step': '5. Disable and re-enable the uplink interface (if applicable)', 'Action': "Run the 'interface uplink shutdown' and 'interface uplink no shutdown' commands to disable and re-enable the interface."}

Post-Check Verification

```
show interface uplink status
show interface uplink counters
show qos profile
show traffic statistics
```