

Ericsson Access Switch (Chennai-TN-92) Alarm Handling Procedure for ALARM_9087

Node: Ericsson-Access-Chennai-TN-92 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_9087

Description

This document outlines the standard operating procedure for handling ALARM_9087 (Warning) on Ericsson Access Switch (Role: Access Switch, Node ID: Ericsson-Access-Chennai-TN-92, Vendor: Ericsson) in the Chennai-TN-92 site.

Potential Root Causes

Cause	Probability
High CPU utilization on the access switch due to excessive packet processing	High
Misconfigured Quality of Service (QoS) settings	Medium
Outdated software or firmware on the access switch	Low

Diagnostic Commands

```
show system resources cpu
show qos statistics
show software version
show run | include qos
```

Resolution Steps

- Step 1: {'Step': 'Check CPU utilization and packet processing rates using show system resources cpu command.', 'Action': 'Verify if CPU utilization is above 80% for an extended period.'}
- Step 2: {'Step': 'Verify QoS settings using show qos statistics command.', 'Action': 'Adjust or reconfigure QoS settings as needed to ensure proper traffic prioritization and handling.'}
- Step 3: {'Step': 'Update software or firmware on the access switch using the upgrade software command.', 'Action': 'Perform a backup of the current configuration before upgrading.'}

Post-Check Verification

```
show system resources cpu
show qos statistics
show software version
```