

Ericsson Access Switch Chennai TN 92 ALARM_9445

Major Alarm SOP

Node: Ericsson-Access-Chennai-TN-92 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_9445

Description

This SOP outlines the procedures to diagnose and resolve the ALARM_9445 Major alarm on Ericsson Access Switch Chennai TN 92.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Incorrect Configuration	Medium
Hardware Failure	Low

Diagnostic Commands

```
show cpu utilization
show config
show hw info
show alarm history
```

Resolution Steps

- Step 1: {'Step': 1, 'Action': 'Check CPU utilization and adjust configuration if necessary.', 'CLI_Command': 'set cpu util adjustment'}
- Step 2: {'Step': 2, 'Action': 'Verify configuration and correct any errors.', 'CLI_Command': 'show config'}
- Step 3: {'Step': 3, 'Action': 'Perform hardware checks and replace faulty equipment if necessary.', 'CLI_Command': 'show hw info'}
- Step 4: {'Step': 4, 'Action': 'Clear alarm history and re-enable alarm reporting.', 'CLI_Command': 'clear alarm history'}

Post-Check Verification

```
show alarm status
show config
show cpu utilization
```

```
show hw info
```