

Ericsson Access Switch Alarm Resolution SOP

Node: Ericsson-Access-Chennai-TN-98 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_6324

Description

This SOP outlines the steps to diagnose and resolve the ALARM_6324 (Warning) on Ericsson Access Switch at Chennai location.

Potential Root Causes

Cause	Probability
Incorrect configuration of the access switch	Medium
Hardware failure of the access switch	Low
Software issue with the access switch	High

Diagnostic Commands

```
show system status
show interface status
show config
show logging
show alarms
```

Resolution Steps

- Step 1: {'Step': '1. Check the system logs for any error messages related to the alarm.', 'Action': 'show logging | grep ALARM_6324'}
- Step 2: {'Step': '2. Verify the interface status and configuration.', 'Action': 'show interface status | include '}
- Step 3: {'Step': '3. Check the access switch configuration.', 'Action': 'show config | include '}
- Step 4: {'Step': '4. Perform a software reload.', 'Action': 'reload force'}
- Step 5: {'Step': '5. If still persisting, perform a hardware check.', 'Action': 'show system status | include '}

Post-Check Verification

```
show system status
show interface status
show config
```

```
show logging
```