

Ericsson Access Switch Alarm SOP - ALARM_6455

Node: Ericsson-Access-Chennai-TN-98 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_6455

Description

This Standard Operating Procedure (SOP) outlines the steps to diagnose and resolve the ALARM_6455 (Warning) on the Ericsson Access Switch at the Chennai TN site (Node ID: Ericsson-Access-Chennai-TN-98).

Potential Root Causes

Cause	Probability
High CPU utilization on the access switch	High
Misconfigured Quality of Service (QoS) settings	Medium
Inadequate memory on the access switch	Low

Diagnostic Commands

```
show system resources cpu
show system resources memory
show qos configuration
show running-config | include QoS
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU utilization', 'Description': "Use the 'show system resources cpu' command to verify CPU utilization. If CPU utilization is high, proceed to Step 2.", 'Action': 'show system resources cpu'}
- Step 2: {'Step': '2. Adjust QoS settings', 'Description': "Adjust QoS settings to prioritize critical traffic. Use the 'configure qos' command to make changes.", 'Action': 'configure qos priority critical'}
- Step 3: {'Step': '3. Check memory utilization', 'Description': "Use the 'show system resources memory' command to verify memory utilization. If memory utilization is high, proceed to Step 4.", 'Action': 'show system resources memory'}
- Step 4: {'Step': '4. Upgrade access switch memory', 'Description': 'Upgrade the access switch memory to meet the recommended configuration.', 'Action': 'system upgrade memory'}

Post-Check Verification

```
show system resources cpu
```

```
show system resources memory  
show qos configuration
```