

Ericsson Access Switch Alarm Resolution SOP

Node: Ericsson-Access-Chennai-TN-98 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_6922

Description

This Standard Operating Procedure (SOP) outlines the steps to diagnose and resolve a Critical Alarm (ALARM_6922) on the Ericsson Access Switch (Node ID: Ericsson-Access-Chennai-TN-98).

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Configuration Issues	Medium
Environmental Factors (Temperature, Power Supply)	Low

Diagnostic Commands

```
show alarm history 6922
show system resources
show interface all status
show configuration | grep ALARM_6922
```

Resolution Steps

Step 1: {'Step': '1. Check Hardware Logs and System Resources', 'Description': 'Verify if there are any hardware-related issues or system resource constraints that could be causing the alarm.', 'Command': 'show system resources'}

Step 2: {'Step': '2. Inspect Interface Status', 'Description': 'Verify the status of all interfaces to check for any physical or link issues.', 'Command': 'show interface all status'}

Step 3: {'Step': '3. Review Configuration Files', 'Description': 'Verify if there are any configuration issues that could be causing the alarm.', 'Command': 'show configuration | grep ALARM_6922'}

Step 4: {'Step': '4. Perform a Hardware Reset', 'Description': 'Perform a hardware reset of the access switch to clear any transient issues.', 'Command': 'reset hardware'}

Step 5: {'Step': '5. Verify Alarm Status', 'Description': 'Verify if the alarm is cleared after the resolution steps.', 'Command': 'show alarm history 6922'}

Post-Check Verification

```
show alarm history 6922
```

```
show system resources
show interface all status
show configuration | grep ALARM_6922
```