

Ericsson Access Switch Alarm SOP - ALARM_9376

Node: Ericsson-Access-Chennai-TN-98 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_9376

Description

This SOP outlines the steps to identify, diagnose, and resolve the ALARM_9376 issue on the Ericsson Access Switch in Chennai, TN-98.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software glitch	Medium
Configuration Error	Low

Diagnostic Commands

```
show system internal alarm
show system internal alarm detail ALARM_9376
show hardware status
show software version
```

Resolution Steps

- Step 1: {'Step': 1, 'Action': 'Perform a hardware reset', 'CLI_Command': 'reset system'}
- Step 2: {'Step': 2, 'Action': 'Check and replace faulty hardware components', 'CLI_Command': 'show hardware status'}
- Step 3: {'Step': 3, 'Action': 'Update software to the latest version', 'CLI_Command': 'install software /nvram:flash/ericsson-os-image.tgz'}
- Step 4: {'Step': 4, 'Action': 'Verify configuration and correct any errors', 'CLI_Command': 'show configuration'}

Post-Check Verification

```
show system internal alarm
show system internal alarm detail ALARM_9376
show hardware status
show software version
```