

Standard Operating Procedure for Ericsson Access Switch Alarm ALARM_1163

Node: Ericsson-Access-Delhi-NCR-14 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_1163

Description

Alarm Description: ALARM_1163 indicates a minor issue on Ericsson Access Switch Node ID: Ericsson-Access-Delhi-NCR-14.

Potential Root Causes

Cause	Probability
Incorrect configuration of the Access Switch.	Medium
Hardware failure in the Access Switch.	Low
Software mismatch or upgrade issue.	Medium

Diagnostic Commands

```
show tech-support
show configuration | include ALARM_1163
show interface | include errors
show version
```

Resolution Steps

- Step 1: {'Step': 'Verify the configuration of the Access Switch.', 'Action': "Check the configuration using the command 'show configuration | include ALARM_1163'.", 'CLI_Command': 'show configuration | include ALARM_1163'}
- Step 2: {'Step': 'Check for any hardware issues.', 'Action': "Run the command 'show interface | include errors' to verify if there are any hardware-related errors.", 'CLI_Command': 'show interface | include errors'}
- Step 3: {'Step': 'Perform a software upgrade if necessary.', 'Action': "Check the version of the software using the command 'show version'. If the software version is outdated, perform a software upgrade.", 'CLI_Command': 'show version'}
- Step 4: {'Step': 'Reset the Access Switch if all else fails.', 'Action': "Reset the Access Switch using the command 'reset' if the issue persists.", 'CLI_Command': 'reset'}

Post-Check Verification

```
show tech-support
show configuration | include ALARM_1163
show interface | include errors
show version
```