

Ericsson Access Node SOP: Resolving Alarm 3659

Node: Ericsson-Access-Delhi-NCR-14 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_3659

Description

Procedure to diagnose, resolve, and verify the fix for Alarm 3659 on Ericsson Access Node Ericsson-Access-Delhi-NCR-14.

Potential Root Causes

Cause	Probability
Incorrect configuration of radio interface	Medium
Faulty or incompatible radio equipment	Low
Software issues or bugs	Medium

Diagnostic Commands

```
show radio interface
show radio config
show system info
show diagnostic result
```

Resolution Steps

- Step 1: {'Step': 'Check radio interface configuration', 'Action': "Verify and correct the radio interface configuration using the 'configure radio interface' command.", 'CLI_Command': 'configure radio interface'}
- Step 2: {'Step': 'Replace faulty or incompatible equipment', 'Action': 'Identify and replace the faulty or incompatible equipment with new or compatible equipment.', 'CLI_Command': ''}
- Step 3: {'Step': 'Update software or firmware', 'Action': 'Update the software or firmware to the latest version to resolve any software issues or bugs.', 'CLI_Command': 'install software'}
- Step 4: {'Step': 'Restart the radio interface', 'Action': 'Restart the radio interface to apply any changes made.', 'CLI_Command': 'restart radio interface'}

Post-Check Verification

```
show radio interface
show radio config
show system info
```

show diagnostic result