

Ericsson Access Switch Alarm SOP: ALARM_9601

Node: Ericsson-Access-Delhi-NCR-14 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_9601

Description

This Standard Operating Procedure (SOP) outlines the steps to be taken when an ALARM_9601 (Warning) occurs on Ericsson Access Switch, Node ID: Ericsson-Access-Delhi-NCR-14.

Potential Root Causes

Cause	Probability
Physical Layer Issues	High
Software Faults	Medium
Configuration Errors	Low

Diagnostic Commands

```
show system redundancy
show interface
show log messages | include ALARM_9601
show version
```

Resolution Steps

- Step 1: {'Step': '1. Check Physical Layer', 'Action': 'Verify that all cables are securely connected and functioning properly.'}
- Step 2: {'Step': '2. Check Software', 'Action': 'Verify that the software version is up-to-date and there are no software faults.'}
- Step 3: {'Step': '3. Check Configuration', 'Action': 'Verify that the configuration is correct and there are no configuration errors.'}
- Step 4: {'Step': '4. Perform Interface Reset', 'Action': '"Use the command 'clear interface ' to reset the interface.'}
- Step 5: {'Step': '5. Restart the Node', 'Action': '"Use the command 'reboot system' to restart the node.'}

Post-Check Verification

```
show system redundancy
show interface
```

```
show log messages | include ALARM_9601  
show version
```