

Ericsson Access Switch Node ID: Ericsson-Access-Delhi-NCR-28 Alarm Resolution SOP

Node: Ericsson-Access-Delhi-NCR-28 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_1220

Description

Resolving critical alarm ALARM_1220 on Ericsson Access Switch Node Ericsson-Access-Delhi-NCR-28

Potential Root Causes

Cause	Probability
Hardware Failure	High
Configuration Error	Medium
Software Glitch	Low

Diagnostic Commands

```
show version
show system resources
show alarm history
show interface status
```

Resolution Steps

- Step 1: {'Step': '1. Power cycle the node', 'CLI_Command': 'power cycle'}
- Step 2: {'Step': '2. Check for hardware issues', 'CLI_Command': 'show system resources | include memory', 'Description': 'Verify if there are any hardware issues that could be causing the alarm'}
- Step 3: {'Step': '3. Check configuration files for errors', 'CLI_Command': 'show configuration', 'Description': 'Verify if there are any configuration errors that could be causing the alarm'}
- Step 4: {'Step': '4. Check for software updates', 'CLI_Command': 'show software versions', 'Description': 'Verify if there are any software updates available that could resolve the issue'}
- Step 5: {'Step': '5. Replace faulty hardware component', 'CLI_Command': '', 'Description': 'If hardware issue is found, replace the faulty component'}

Post-Check Verification

```
show alarm history  
show interface status  
show system resources
```