

Standard Operating Procedure for Resolving ALARM_1225 on Ericsson-Access-Delhi-NCR-28

Node: Ericsson-Access-Delhi-NCR-28 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_1225

Description

ALARM_1225 on Ericsson-Access-Delhi-NCR-28 is a Major Severity Alarm indicating a critical issue with the Access Switch.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Glitch	Medium
Configuration Issues	Low

Diagnostic Commands

```
show alarms detail ALARM_1225
show system info
show hardware status
show software version
```

Resolution Steps

- Step 1: {'Step': 'Restart the Access Switch', 'Command': 'reboot system'}
- Step 2: {'Step': 'Check and Replace Faulty Hardware', 'Command': 'show hardware status'}
- Step 3: {'Step': 'Update Software Version', 'Command': 'software update install'}
- Step 4: {'Step': 'Review and Correct Configuration', 'Command': 'show configuration'}

Post-Check Verification

```
show alarms detail ALARM_1225
show system info
show hardware status
show software version
```