

Standard Operating Procedure for ALARM_1928

Alarm on Ericsson Access Switch - Delhi NCR-28

Node: Ericsson-Access-Delhi-NCR-28 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_1928

Description

This SOP outlines the steps to be taken for resolving the ALARM_1928 alarm on the Ericsson Access Switch, Node ID: Ericsson-Access-Delhi-NCR-28.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Configuration Error	Medium
Hardware Failure	Low

Diagnostic Commands

```
show system status
show cpu usage
show configuration | include
```

Resolution Steps

- Step 1: {'Step': "Check CPU utilization using 'show cpu usage' command and take necessary action to reduce it.", 'Action': "Execute command 'show cpu usage' and analyze the output."}
- Step 2: {'Step': "Verify configuration for ALARM_1928 alarm using 'show configuration | include ' command.", 'Action': "Execute command 'show configuration | include ' and verify if configuration is correct."}
- Step 3: {'Step': 'Clear the alarm and reboot the switch if necessary.', 'Action': "Execute command 'clear alarm ' to clear the alarm and reboot the switch if required."}

Post-Check Verification

```
show alarm status
show system status
```