

Ericsson Access Switch Alarm SOP (ALARM_3435)

Node: Ericsson-Access-Delhi-NCR-28 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_3435

Description

This SOP outlines the steps to diagnose and resolve a Critical alarm (ALARM_3435) on Ericsson Access Switch at Node ID: Ericsson-Access-Delhi-NCR-28.

Potential Root Causes

Cause	Probability
Physical layer issues (e.g., cable damage, port malfunction)	High
Software configuration errors or bugs	Medium
Environmental factors (e.g., temperature, power supply issues)	Low

Diagnostic Commands

```
show tech support
show version
show port status
show interface detail
show log | include ALARM_3435
```

Resolution Steps

- Step 1: { 'Step': 'Verify physical connections and check for cable damage.', 'Action': 'Inspect cables and connections to the Access Switch.' }
- Step 2: { 'Step': 'Run diagnostic tests on the affected port.', 'Action': 'execute port diagnostic test' }
- Step 3: { 'Step': 'Check software configuration for errors or inconsistencies.', 'Action': 'show run | include ALARM_3435' }
- Step 4: { 'Step': 'Update software or firmware if necessary.', 'Action': 'upgrade software or firmware' }
- Step 5: { 'Step': 'Reset the Access Switch to default configuration.', 'Action': 'reset system default' }

Post-Check Verification

```
show log | include ALARM_3435
show port status
show interface detail
```

```
show version
```