

SOP - Ericsson Access Switch Delhi NCR 28

ALARM_4166

Node: Ericsson-Access-Delhi-NCR-28 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_4166

Description

This SOP outlines the procedures to diagnose and resolve the ALARM_4166 (Minor Severity) on Ericsson Access Switch Delhi NCR 28.

Potential Root Causes

Cause	Probability
Incorrect configuration of the Access Switch	Medium
Hardware failure of the Access Switch	Low
Software bug or mismatch	High

Diagnostic Commands

```
show version
show tech support
show logs
show alarms
```

Resolution Steps

- Step 1: {'Step': '1. Check the Access Switch configuration', 'Action': "Verify the configuration using the 'show configuration' command and compare it with the recommended settings."}
- Step 2: {'Step': '2. Check for software updates', 'Action': "Verify if the software is up-to-date using the 'show version' command and apply any available updates."}
- Step 3: {'Step': '3. Check for hardware issues', 'Action': "Run the 'show tech support' command to check for any hardware-related issues and replace faulty components if necessary."}
- Step 4: {'Step': '4. Check for software bugs or mismatches', 'Action': "Run the 'show logs' command to check for any software-related issues and apply any available patches or updates."}
- Step 5: {'Step': '5. Reset the Access Switch', 'Action': "Reset the Access Switch using the 'reset' command to restore the default settings."}

Post-Check Verification

```
show status
```

```
show alarms
```

```
show logs
```