

Ericsson Access Switch Alarm SOP: ALARM_4572

Node: Ericsson-Access-Delhi-NCR-28 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_4572

Description

Minor alarm indicating a potential issue on Ericsson Access Switch Node ID: Ericsson-Access-Delhi-NCR-28.

Potential Root Causes

Cause	Probability
Optical Fiber Damage	Medium
Transponder Module Failure	High
Software Configuration Issue	Low

Diagnostic Commands

```
show transponder status
show optical fiber status
show transponder logs
show software version
```

Resolution Steps

- Step 1: {'Step': 'Run diagnostic commands to identify root cause', 'Actions': ['Run show transponder status command to check transponder status', 'Run show optical fiber status command to check optical fiber status']}
- Step 2: {'Step': 'Replace transponder module if failed', 'Actions': ['Enter maintenance mode', 'Replace transponder module', 'Verify replacement module is functioning correctly']}
- Step 3: {'Step': 'Review and adjust software configuration if necessary', 'Actions': ['Review software configuration', 'Adjust software configuration as necessary', 'Verify software configuration update']}

Post-Check Verification

```
show transponder status
show optical fiber status
show transponder logs
show software version
```