

SOP for Resolving ALARM_5518 on Ericsson Access Switch

Node: Ericsson-Access-Delhi-NCR-28 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_5518

Description

This SOP outlines the steps to resolve a minor alarm ALARM_5518, a temperature alarm, on the Ericsson Access Switch deployed in Delhi NCR region.

Potential Root Causes

Cause	Probability
High Ambient Temperature	High
Faulty Temperature Sensor	Medium
Software Glitch	Low

Diagnostic Commands

```
show environment temp
show sensors
show system status
```

Resolution Steps

Step 1: {'Step': '1. Check Ambient Temperature', 'Action': 'Verify the ambient temperature of the equipment room and ensure it is within the recommended range.', 'CLI_Commands': 'show environment temp'}

Step 2: {'Step': '2. Replace Faulty Temperature Sensor', 'Action': 'Physically inspect the temperature sensor and replace it if faulty.', 'CLI_Commands': 'show sensors'}

Step 3: {'Step': '3. Reload Switch Software', 'Action': 'Reload the switch software to resolve any software glitches.', 'CLI_Commands': 'reload software'}

Post-Check Verification

```
show environment temp
show sensors
show system status
```