

Ericsson Access Switch Alarm Resolution SOP

Node: Ericsson-Access-Delhi-NCR-28 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_6154

Description

This SOP outlines the steps to resolve the ALARM_6154 warning on the Ericsson Access Switch in Delhi NCR Node ID: Ericsson-Access-Delhi-NCR-28.

Potential Root Causes

Cause	Probability
High CPU Utilization	High
Insufficient Memory	Medium
Misconfigured Routing Protocol	Low

Diagnostic Commands

```
show cpu utilization
show memory
show routing protocol statistics
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU Utilization', 'Action': "Run 'show cpu utilization' command to identify if CPU utilization is high."}
- Step 2: {'Step': '2. Check Memory Utilization', 'Action': "Run 'show memory' command to check if memory is insufficient."}
- Step 3: {'Step': '3. Check Routing Protocol Configuration', 'Action': "Run 'show routing protocol statistics' command to identify if routing protocol is misconfigured."}
- Step 4: {'Step': '4. Adjust CPU and Memory Resources', 'Action': 'Adjust CPU and memory resources as needed to resolve high CPU utilization and insufficient memory.'}
- Step 5: {'Step': '5. Reconfigure Routing Protocol', 'Action': 'Reconfigure routing protocol to resolve misconfiguration.'}

Post-Check Verification

```
show cpu utilization
show memory
show routing protocol statistics
```