

Ericsson Access Switch SOP for ALARM_9030

Node: Ericsson-Access-Delhi-NCR-28 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_9030

Description

This SOP outlines the steps to troubleshoot and resolve the ALARM_9030 on Ericsson Access Switch Node ID: Ericsson-Access-Delhi-NCR-28.

Potential Root Causes

Cause	Probability
Incorrect configuration of the access switch	High
Hardware failure in the access switch	Medium
Software issue in the access switch	Low

Diagnostic Commands

```
show system general
show board status
show config access-switch
```

Resolution Steps

- Step 1: {'Step': 'Check the system logs for any error messages', 'Action': 'show system log'}
- Step 2: {'Step': 'Verify the access switch configuration', 'Action': 'show config access-switch'}
- Step 3: {'Step': 'Perform a hardware check', 'Action': 'show board status'}
- Step 4: {'Step': 'Reboot the access switch', 'Action': 'reboot'}
- Step 5: {'Step': 'If the issue persists, contact Ericsson support'}

Post-Check Verification

```
show system general
show board status
show config access-switch
```