

SOP for Resolving Ericsson ALARM_5013 on Ericsson-Access-Delhi-NCR-32

Node: Ericsson-Access-Delhi-NCR-32 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_5013

Description

Minor alarm indicating a problem with the Access Switch. This SOP outlines the steps to diagnose and resolve the issue.

Potential Root Causes

Cause	Probability
Hardware failure in the Access Switch	Medium
Software glitch or bug in the Access Switch firmware	Low
Configuration issue or mismatch in the Access Switch	High

Diagnostic Commands

```
show tech support
show diag
show version
show config
```

Resolution Steps

- Step 1: {'Step': "1. Run a 'show tech support' command to gather information about the alarm.", 'Action': 'Use the output to identify the cause of the alarm.'}
- Step 2: {'Step': "2. Check the system logs for any errors or warnings related to the alarm.", 'Action': "Use the 'show log' command to view the system logs."}
- Step 3: {'Step': "3. Verify the configuration of the Access Switch.", 'Action': "Use the 'show config' command to review the configuration."}
- Step 4: {'Step': "4. If the issue is related to a software glitch or bug, attempt to reload the firmware.", 'Action': "Use the 'reload' command to reload the firmware."}
- Step 5: {'Step': "5. If the issue persists, contact Ericsson support for further assistance.", 'Action': 'Provide the output from the diagnostic commands and any other relevant information.'}

Post-Check Verification

```
show tech support
show diag
show version
show config
```