

Standard Operating Procedure: Resolving Ericsson Access Switch Delhi NCR Node 32 Alarm

ALARM_5819

Node: Ericsson-Access-Delhi-NCR-32 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_5819

Description

This SOP outlines the steps to diagnose and resolve a Major alarm on Ericsson Access Switch Delhi NCR Node 32, identified by ALARM_5819.

Potential Root Causes

Cause	Probability
Hardware failure in the switch	High
Software bug in the switch firmware	Medium
Misconfiguration of the switch	Low

Diagnostic Commands

```
show alarm history
show tech support
show system resource utilization
show interface status
```

Resolution Steps

- Step 1: {'Step': '1. Check alarm history and tech support information', 'Action': "Run 'show alarm history' and 'show tech support' CLI commands"}
- Step 2: {'Step': '2. Verify system resource utilization', 'Action': "Run 'show system resource utilization' CLI command"}
- Step 3: {'Step': '3. Check interface status', 'Action': "Run 'show interface status' CLI command"}
- Step 4: {'Step': '4. If hardware issue suspected, perform a hardware swap', 'Action': 'Replace faulty hardware component'}
- Step 5: {'Step': '5. If software issue suspected, update switch firmware to latest version', 'Action': "Run 'install new software' CLI command"}
- Step 6: {'Step': '6. If misconfiguration suspected, verify switch configuration', 'Action': "Run 'show configuration' CLI command"}

Post-Check Verification

```
show alarm history
show system resource utilization
show interface status
```