

Ericsson Access Switch ALARM_9338 Minor Alarm SOP

Node: Ericsson-Access-Delhi-NCR-36 | **Vendor:** Ericsson | **Severity:** Minor | **Alarm Code:** ALARM_9338

Description

This procedure outlines the steps to troubleshoot and resolve a minor alarm ALARM_9338 on the Ericsson Access Switch Node ID: Ericsson-Access-Delhi-NCR-36.

Potential Root Causes

Cause	Probability
Invalid or misconfigured IPoE settings	Medium
Faulty or malfunctioning interface cards	Low
Software or firmware issues	Low

Diagnostic Commands

```
show ipoe settings
show interface status
show card status
show version
show tech-support
```

Resolution Steps

- Step 1: {'Step': 'Check and reconfigure IPoE settings', 'Description': "Use the CLI command 'configure ipoe settings' to reconfigure the IPoE settings.", 'Command': 'configure ipoe settings'}
- Step 2: {'Step': 'Replace faulty interface cards', 'Description': 'Replace the faulty interface cards with new ones and power cycle the node.', 'Command': 'replace card '}
- Step 3: {'Step': 'Update software or firmware', 'Description': 'Check for any software or firmware updates and apply them to the node.', 'Command': 'update software'}

Post-Check Verification

```
show ipoe settings
show interface status
show card status
```

```
show version
show tech-support
```