

SOP: Resolving Ericsson Access Switch Alarm

ALARM_2378 in Kolkata WB Node

Node: Ericsson-Access-Kolkata-WB-114 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_2378

Description

Major Alarm Triggered on Ericsson Access Switch Node Ericsson-Access-Kolkata-WB-114

Potential Root Causes

Cause	Probability
High CPU utilization due to software bugs	High
Misconfigured network interfaces	Medium
Hardware failure due to overheating or physical damage	Low

Diagnostic Commands

```
show alarm all
show cpu utilization
show interface status
show version
```

Resolution Steps

Step 1: {'Step': 'Step 1: Restart the node', 'Action': 'reload', 'CLI_Command': 'reload', 'Note': "This step may resolve the issue if it's due to a software glitch"}

Step 2: {'Step': 'Step 2: Check and configure network interfaces', 'Action': 'Verify and configure network interfaces', 'CLI_Command': 'interface no shutdown', 'Note': 'Make sure all network interfaces are up and configured correctly'}

Step 3: {'Step': 'Step 3: Check for hardware issues', 'Action': 'Perform a thorough hardware inspection', 'CLI_Command': None, 'Note': 'Check for any signs of overheating or physical damage'}

Step 4: {'Step': 'Step 4: Upgrade or downgrade software (if necessary)', 'Action': 'Upgrade or downgrade software', 'CLI_Command': 'software install ', 'Note': 'If the issue is due to a software bug, try upgrading or downgrading the software'}

Post-Check Verification

```
show alarm all
show cpu utilization
```

```
show interface status  
show version
```