

Ericsson Access Switch Node Alarm Resolution SOP (ALARM_2530)

Node: Ericsson-Access-Kolkata-WB-114 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_2530

Description

This SOP outlines the steps to be followed to resolve a critical alarm on Ericsson Access Switch Node Ericsson-Access-Kolkata-WB-114. Alarm ALARM_2530 is associated with a critical issue that requires immediate attention.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Bug	Medium
Configuration Issues	Low

Diagnostic Commands

```
show tech-support
show system info
show hw-module all
show sw-version
```

Resolution Steps

- Step 1: {'Step': 'Power cycle the node', 'Description': 'Perform a hard reboot of the Ericsson Access Switch Node Ericsson-Access-Kolkata-WB-114. This may resolve the issue if it is related to a transient software bug or a hardware failure.', 'CLI_Commands': ['power off', 'power on']}
- Step 2: {'Step': 'Check and update software', 'Description': 'Verify if the software version is up-to-date. If not, update the software to the latest version.', 'CLI_Commands': ['show sw-version', 'install sw-version']}
- Step 3: {'Step': 'Check and correct configuration', 'Description': 'Verify the configuration settings on the node. If any incorrect settings are found, correct them.', 'CLI_Commands': ['show config', 'config set']}

Post-Check Verification

```
show tech-support
show system info
```

```
show hw-module all  
show sw-version
```