

Standard Operating Procedure for Ericsson Access Switch Alarm ALARM_5602

Node: Ericsson-Access-Kolkata-WB-114 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_5602

Description

Alarm ALARM_5602 on Ericsson Access Switch Node ID: Ericsson-Access-Kolkata-WB-114 indicates a critical issue.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Bug	Medium
Configuration Error	Low

Diagnostic Commands

```
show alarm info
show tech-support
show environment
show card status
```

Resolution Steps

Step 1: {'Step': 'Replace faulty hardware component', 'CLI_Commands': ['reload', 'show card status']}

Step 2: {'Step': 'Update software to latest version', 'CLI_Commands': ['software update', 'show software version']}

Step 3: {'Step': 'Verify and correct configuration', 'CLI_Commands': ['show configuration', 'commit']}

Post-Check Verification

```
show alarm info
show card status
show software version
show configuration
```