

Ericsson Access Switch Node

Ericsson-Access-Kolkata-WB-114 Alarm SOP

Node: Ericsson-Access-Kolkata-WB-114 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_9293

Description

This SOP outlines the procedures to be followed in case of a critical alarm ALARM_9293 on Ericsson Access Switch Node Ericsson-Access-Kolkata-WB-114.

Potential Root Causes

Cause	Probability
Hardware Failure	High
Software Glitch	Medium
Configuration issue	Low

Diagnostic Commands

```
show tech-support
show alarm history
debug enable
debug controller
```

Resolution Steps

- Step 1: {'Step': 'Power cycle the node', 'Description': 'Perform a power cycle of the Ericsson Access Switch Node Ericsson-Access-Kolkata-WB-114 to reset the system.', 'CLI_Commands': ['power-off ', 'power-on ']}
- Step 2: {'Step': 'Check for hardware issues', 'Description': 'Inspect the node for any signs of physical damage or malfunctioning components.', 'CLI_Commands': ['show hardware']}
- Step 3: {'Step': 'Update software', 'Description': 'Verify if the software is up-to-date and update it if necessary.', 'CLI_Commands': ['software update']}
- Step 4: {'Step': 'Reconfigure the node', 'Description': 'Reconfigure the node to resolve any configuration issues.', 'CLI_Commands': ['config reload']}

Post-Check Verification

```
show tech-support
show alarm history
```

show hardware