

Ericsson Access Switch Alarm SOP: ALARM_2683 (Warning)

Node: Ericsson-Access-Kolkata-WB-118 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_2683

Description

This SOP outlines the steps to diagnose and resolve the ALARM_2683 (Warning) on the Ericsson Access Switch (Node ID: Ericsson-Access-Kolkata-WB-118).

Potential Root Causes

Cause	Probability
High CPU Usage due to software issues or configuration.	High
Incorrect configuration or misaligned timing with neighboring nodes.	Medium
Hardware issues with the switch or its components.	Low

Diagnostic Commands

```
show cpu usage
show system info
show configuration | include timing
show neighboring nodes
```

Resolution Steps

- Step 1: {'Step': '1. Check CPU Usage and System Info', 'Action': "Run the command 'show cpu usage' and 'show system info' to identify any software issues or configuration problems."}
- Step 2: {'Step': '2. Verify Timing Configuration', 'Action': "Run the command 'show configuration | include timing' to verify the timing configuration is correct."}
- Step 3: {'Step': '3. Check Neighbor Node Alignment', 'Action': "Run the command 'show neighboring nodes' to verify the timing alignment with neighboring nodes."}
- Step 4: {'Step': '4. Restart Switch or Reconfigure as Needed', 'Action': 'Based on the diagnostic results, restart the switch or reconfigure the timing settings as necessary to resolve the issue.'}

Post-Check Verification

```
show cpu usage
show system info
```

```
show configuration | include timing
```