

Ericsson Access Switch SOP for Critical Alarm

ALARM_3199

Node: Ericsson-Access-Kolkata-WB-118 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM_3199

Description

This Standard Operating Procedure outlines the steps to diagnose, resolve, and verify the fix for the Critical Alarm ALARM_3199 on Ericsson Access Switch Node ID: Ericsson-Access-Kolkata-WB-118.

Potential Root Causes

Cause	Probability
Misconfigured Layer 2 protocol parameters	High
Faulty hardware component (e.g., ASIC, CPU)	Medium
Software issue (e.g., bug, incompatible version)	Low

Diagnostic Commands

```
show system alarm detail
show system hardware
show system software
show l2 protocol parameters
```

Resolution Steps

- Step 1: {'Step': 'Check and configure Layer 2 protocol parameters', 'Action': 'configure l2 protocol parameters'}
- Step 2: {'Step': 'Replace faulty hardware component (if identified)', 'Action': 'replace hardware component'}
- Step 3: {'Step': 'Update software to latest version (if necessary)', 'Action': 'update software'}
- Step 4: {'Step': 'Clear and re-enable the affected interface', 'Action': 'clear interface {interface_name} enable'}

Post-Check Verification

```
show system alarm detail
show interface {interface_name} status
show system hardware
```

```
show system software
```