

# Ericsson Access Switch Alarm Resolution SOP

**Node:** Ericsson-Access-Kolkata-WB-118 | **Vendor:** Ericsson | **Severity:** Critical | **Alarm Code:** ALARM\_3835

## Description

This SOP outlines the steps to identify, diagnose, and resolve the ALARM\_3835 on the Ericsson-Access-Kolkata-WB-118 access switch.

## Potential Root Causes

| Cause                                              | Probability |
|----------------------------------------------------|-------------|
| Hardware failure of a critical component           | High        |
| Software corruption or mismatch                    | Medium      |
| Environmental issues (temperature, humidity, etc.) | Low         |

## Diagnostic Commands

```
show system alarm
show system hardware status
show system software version
show system environment status
```

## Resolution Steps

- Step 1: { 'Step': 'Power cycle the access switch', 'Description': 'Perform a hard reset of the access switch to clear any temporary issues.', 'CLI\_Command': 'system restart' }
- Step 2: { 'Step': 'Verify software version', 'Description': 'Ensure that the software version is up-to-date and matches the recommended version.', 'CLI\_Command': 'show system software version' }
- Step 3: { 'Step': 'Replace faulty hardware component', 'Description': 'Replace the critical component that caused the alarm and verify that it resolves the issue.', 'CLI\_Command': 'no system hardware replace ' }
- Step 4: { 'Step': 'Adjust environmental settings', 'Description': 'Adjust the temperature and humidity settings to optimal levels.', 'CLI\_Command': 'system environment adjust ' }

## Post-Check Verification

```
show system alarm
show system hardware status
show system software version
show system environment status
```