

Ericsson Access Switch Alarm SOP: ALARM_8839

Node: Ericsson-Access-Kolkata-WB-118 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_8839

Description

This SOP outlines the steps to diagnose and resolve the ALARM_8839, a major alarm indicating a critical issue on Ericsson Access Switch Node ID: Ericsson-Access-Kolkata-WB-118.

Potential Root Causes

Cause	Probability
High CPU utilization due to software bugs or misconfiguration.	High
Misconfigured or faulty network interface cards (NICs) or line cards.	Medium
Hardware or software failure, resulting in system instability.	Low

Diagnostic Commands

```
show version
show system resources
show interface
show process memory
show process cpu
```

Resolution Steps

- Step 1: {'Step': '1. Check system resources and identify the source of high CPU utilization.', 'Action': "Run 'show system resources' command and analyze the output."}
- Step 2: {'Step': '2. Verify NIC or line card configuration.', 'Action': "Run 'show interface ' command and check for any misconfigurations."}
- Step 3: {'Step': '3. Perform hardware or software reset.', 'Action': "Run 'reset system' or 'boot system' command, depending on the required action."}
- Step 4: {'Step': '4. Reboot the system and monitor for alarm recurrence.', 'Action': "Run 'reboot system' command and verify if the alarm persists."}

Post-Check Verification

```
show system resources
show interface
show process memory
```

```
show process cpu
```