

Ericsson Access Switch ALARM_9744 Root Cause and Resolution SOP

Node: Ericsson-Access-Kolkata-WB-118 | **Vendor:** Ericsson | **Severity:** Major | **Alarm Code:** ALARM_9744

Description

This SOP outlines the steps to diagnose and resolve the Major Alarm ALARM_9744 on the Ericsson Access Switch Node ID: Ericsson-Access-Kolkata-WB-118.

Potential Root Causes

Cause	Probability
Physical Layer Fault	High
Optical Fiber Damage	Medium
Electrical Interface Issue	Low

Diagnostic Commands

```
show interface ae1/1/0/1
show interface ae1/1/0/1 detail
show alarm history
show environment temperature
```

Resolution Steps

- Step 1: {'Step': 'Perform Physical Layer Check', 'Description': 'Verify the physical connections and cable integrity.', 'Commands': []}
- Step 2: {'Step': 'Swap Optical Fiber', 'Description': 'Swap the optical fiber and re-check the alarm.', 'Commands': []}
- Step 3: {'Step': 'Reset Electrical Interface', 'Description': 'Reset the electrical interface to its default settings.', 'Commands': ['interface ae1/1/0/1', 'reset']}

Post-Check Verification

```
show interface ae1/1/0/1
show alarm history
show environment temperature
```