

Ericsson Access Switch SOP for Alarm Code

ALARM_3984

Node: Ericsson-Access-Kolkata-WB-124 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_3984

Description

This SOP outlines the steps to diagnose and resolve the Alarm Code ALARM_3984 on Ericsson Access Switch Node ID Ericsson-Access-Kolkata-WB-124.

Potential Root Causes

Cause	Probability
High CPU utilization on the access switch due to excessive packet processing	High
Misconfiguration of QoS policies leading to packet drops	Medium
Hardware issues with the access switch's packet processing capabilities	Low

Diagnostic Commands

```
show system cpu usage
show qos policy
show packet drops
show hardware status
```

Resolution Steps

- Step 1: {'Step': 'Verify CPU utilization levels', 'Action': "Run the command 'show system cpu usage' to check if CPU utilization is above 70%", 'CLI_Command': 'show system cpu usage'}
- Step 2: {'Step': 'Check QoS policy configuration', 'Action': 'Verify that QoS policies are correctly configured and not leading to packet drops', 'CLI_Command': 'show qos policy'}
- Step 3: {'Step': 'Clear packet drops', 'Action': "Run the command 'clear packet drops' to clear any existing packet drops", 'CLI_Command': 'clear packet drops'}
- Step 4: {'Step': 'Replace faulty hardware', 'Action': 'Replace the access switch if hardware issues are detected', 'CLI_Command': ''}

Post-Check Verification

```
show system cpu usage
show qos policy
```

```
show packet drops  
show hardware status
```