

Alarm Response Procedure for Ericsson Access Switch ALARM_7376

Node: Ericsson-Access-Kolkata-WB-124 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_7376

Description

This SOP outlines the steps to be taken when the Ericsson Access Switch ALARM_7376 is triggered, indicating a Warning condition.

Potential Root Causes

Cause	Probability
Incorrect Configuration	High
Hardware Failure	Medium
Software Issue	Low

Diagnostic Commands

```
show alarm ALARM_7376
show tech-support
show run | include ALARM_7376
show system resource
```

Resolution Steps

- Step 1: {'Step': 'Check the configuration', 'Action': 'Verify the configuration for the Ericsson Access Switch using the command `show run | include ALARM\_7376`'}
- Step 2: {'Step': 'Verify the hardware', 'Action': 'Run the command `show system resource` to check for any hardware issues'}
- Step 3: {'Step': 'Check the logs', 'Action': 'Run the command `show tech-support` to check for any software or configuration issues'}
- Step 4: {'Step': 'Reboot the switch', 'Action': 'Use the command `reload` to reboot the Ericsson Access Switch'}
- Step 5: {'Step': 'Verify the fix', 'Action': 'Run the command `show alarm ALARM\_7376` to verify if the alarm has cleared'}

Post-Check Verification

```
show alarm ALARM_7376
show run | include ALARM_7376
show system resource
```