

Ericsson Access Switch ALARM_4631 - Warning: Potential BFD Session Establishment Issue

Node: Ericsson-Access-Kolkata-WB-128 | **Vendor:** Ericsson | **Severity:** Warning | **Alarm Code:** ALARM_4631

Description

ALARM_4631 is triggered when there is a potential issue with establishing BFD (Bidirectional Forwarding Detection) sessions on Ericsson Access Switch.

Potential Root Causes

Cause	Probability
Misconfigured BFD session parameters	High
Incompatible BFD mode or version	Medium
BFD session establishment timeout	Low

Diagnostic Commands

```
show bfd sessions
show bfd configuration
show bfd statistics
```

Resolution Steps

- Step 1: {'Step': 'Verify BFD session parameters', 'Action': "Check if BFD session parameters are properly configured using 'show bfd configuration' command"}
- Step 2: {'Step': 'Check BFD mode and version', 'Action': "Verify if BFD mode and version are compatible using 'show bfd configuration' command"}
- Step 3: {'Step': 'Reset BFD session establishment', 'Action': "Reset BFD session establishment using 'clear bfd sessions' command and verify using 'show bfd sessions' command"}

Post-Check Verification

```
show bfd sessions
show bfd statistics
```